

Torque Caravan Services

Service Prices



- Servicing
- Jayco Warranty Repairs
- Roll-out Awning Repairs
- RV Accessory Fitting



81 Secam Street, Mansfield, Qld, 4122 | Phone: 07 3343 5912

www.torquecaravanservices.com.au

We service all brands of caravans, campers and RVs



Caravan & Camper Service Checklist

Service – 12 month

Single Axle	Tandem Axle
\$418.00	\$440.00

INTERIOR

- Check security of appliance
- 240V test – Interior lighting
- Adjust cupboard catches
- 12V Fridge test
- Campers – service winder mechanism and components
- Smoke alarm test

PLUMBING SYSTEM

- Test for water leaks on mains pressure
- Test for water leaks on 12V pump – if applicable
- Check sink waste (drain)

*GAS SYSTEM

- Test operation of cooker
- Test operation of refrigerator
- Test operation of gas hot water system
- Check Anode
- Replace Anode if required – Additional Charge

BODY

- Lube all locks

WHEELS & TYRES

- Inspect tread wear
- Inspect rims for dents
- Tighten wheel nuts
- Re-paint hubs
- Adjust tyre pressures – incl spare

WHEEL BEARINGS

- Inspect bearings for uneven wear
- Wash bearing
- Re-pack bearings with new grease
- Replace bearing seats
- Replace split pins

Caravan Down Ball Weight _____ Kg

BRAKES

- Adjust handbrake travel
- Adjust brakes
- Inspect electric brake magnets
- Inspect brake linings & adjust as required
- Test brake safe – if applicable

CHASSIS

- Check coupling bolts & tighten as required
- Re-paint coupling
- Oil corner jacks
- Grease jockey wheel clamp
- Grease jockey wheel bearing

SUSPENSION

Leaf Spring

- Inspect suspension mounts
- Re-grease suspension nipples
- Tension U-bolts to required torque

Coil Spring Independent

- Check tension pivot bolts
- Check condition of pivot bolts
- Check tension shock absorber bolts
- Check condition of shock strap
- Check condition of shock absorbers
- Check condition of shock absorber bushes
- Check condition of aeon spring aid
- Grease control arm pivots
- Check tyres for abnormal wear
- Visual inspection of control arms
- Visual inspection of suspension chassis

EXTERNAL WORKING LIGHTS

- Test indicators
- Test brake lights
- Test tail lights
- Test running/clearance lights

NITROGEN PLUS PRICES

Single Axle new fills - \$12.48/tyre x 3	\$37.44
Single Axle re-fills - \$7.48/tyre x 3	\$22.44
Tandem Axle new fills - \$12.48/tyre x 5	\$62.40
Tandem Axle re-fills - \$7.48/tyre x 5	\$37.40

** When performing gas appliance operation tests, in the instance that a fault is identified, we will notify you of this issue and offer the service of an independent gas fitter to rectify this issue at an additional fee to the standard service fee*