

# Torque Caravan Services

## Service Details



- Servicing
- Warranty Repairs
- Roll-out Awning Repairs
- RV Accessory Fitting



Phone: 0419 670 161

[www.torquecaravanservices.com.au](http://www.torquecaravanservices.com.au)

**We service all brands of caravans, campers and RVs**

# Caravan & Camper Service Checklist

## Service – 12 month

### INTERIOR

- Check security of appliance
- 240V test – Interior lighting
- Adjust cupboard catches
- 12V Fridge test
- Campers – service winder mechanism and components
- Smoke alarm test

### PLUMBING SYSTEM

- Test for water leaks on mains pressure
- Test for water leaks on 12V pump – if applicable
- Check sink waste (drain)

### \*GAS SYSTEM

- Test operation of cooker
- Test operation of refrigerator
- Test operation of gas hot water system
- Check Anode
- Replace Anode if required – Additional Charge

### BODY

- Lube all locks

### WHEELS & TYRES

- Inspect tread wear
- Inspect rims for dents
- Tighten wheel nuts
- Re-paint hubs
- Adjust tyre pressures – incl spare

### WHEEL BEARINGS

- Inspect bearings for uneven wear
- Wash bearing
- Re-pack bearings with new grease
- Replace bearing seats
- Replace split pins

Caravan Down Ball Weight \_\_\_\_\_ Kg

### BRAKES

- Adjust handbrake travel
- Adjust brakes
- Inspect electric brake magnets
- Inspect brake linings & adjust as required
- Test brake safe – if applicable

### CHASSIS

- Check coupling bolts & tighten as required
- Re-paint coupling
- Oil corner jacks
- Grease jockey wheel clamp
- Grease jockey wheel bearing

### SUSPENSION

#### Leaf Spring

- Inspect suspension mounts
- Re-grease suspension nipples
- Tension U-bolts to required torque

#### Coil Spring Independent

- Check tension pivot bolts
- Check condition of pivot bolts
- Check tension shock absorber bolts
- Check condition of shock strap
- Check condition of shock absorbers
- Check condition of shock absorber bushes
- Check condition of aeon spring aid
- Grease control arm pivots
- Check tyres for abnormal wear
- Visual inspection of control arms
- Visual inspection of suspension chassis

### EXTERNAL WORKING LIGHTS

- Test indicators
- Test brake lights
- Test tail lights
- Test running/clearance lights

### NITROGEN PLUS PRICES

Single Axel new fills - \$12.48/tyre x 3	\$37.44
Single Axle re-fills - \$7.48/tyre x 3	\$22.44
Tandem Axle new fills - \$12.48/tyre x 5	\$62.40
Tandem Axle re-fills - \$7.48/tyre x 5	\$37.40

*\* When performing gas appliance operation tests, in the instance that a fault is identified, we will notify you of this issue and offer the service of an independent gas fitter to rectify this issue at an additional fee to the standard service fee*